

Part-I

Performa for the Safety School Building
(To be filled by the Head of School/ Institute)

1. Name of School : St. Martha's Bethany Vidyalaya
2. Location : Rurka, Mullanpur, Ludhiana
3. Plot Area : 4.00 Acres
4. Plinth Area : 41817 sq.ft.
5. Number of Storey : Ground Floor + First Floor
6. Year of Construction of Building : 2015
7. Supervision of the qualified Engineer.
The following details may be given :
 - a) Name of the Engineer : Er. Harpreet Singh
 - b) Address : BRS Nagar, Ludhiana
 - c) Set of Structure Drawing used in the construction if available : Attached
 - d) Name of the Architect : Er. Harpreet Singh
8. Whether the building has been constructed for the purpose of :
 - a) School (Yes/ No) *yes*
 - b) Residential purpose and converted for use as a school (Yes/ No) *No*
9. Materials used for Roof :
 - a) R.C.C Slabs (Yes/ No) *yes*
 - b) R.S. Joists and Battens (Yes/ No) *No*
 - c) Wooden Joists and Battens (Yes/ No) *No*
10. Materials used for walls :
 - a) Mud Mortar (Yes/ No) *No*
 - b) Cement Mortar (Yes/ No) *yes*
 - c) Plaster (i) Lime Mortar (Yes/ No) *No*
(ii) Cement Mortar (Yes/ No) *yes*
11. Flooring:
 - a) Conglomerate (Yes/ No) *No*
 - b) Terrazzo (Yes/ No) *yes*
 - c) Brick Paving (Yes/ No) *No*
12. Detailed Drawing indicating dimensions of the rooms along with size and location of doors and windows

Attached

Principal with stamp of
St. Martha's Bethany Vidyalaya
Affiliated to CBSE No.1631272
Rurka Kalan, Mullanpur
Distt. Ludhiana-141101 (Pb.) India

Part-II
(To be filled by S.D.E. of P.W.D B&R Department)

I have visited the above mentioned school on 05/05/23 and have visually inspected it from all angles of safety and I found it fit for normal use as school building.

In case any addition/ alteration of expansion and modification of this building is to be carried out the same be carried out under the supervision of a technically specified Engineer and this certificate may again be obtained after the completion of work from the undersigned.

In case the building is affected by flood or if there is settlement of walls/ foundations or caves of roof etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.

This building can be safely occupied for normal use up to 31/03/2027 (indicate year up to which it can be used) MARCH-2027

Receipt No. 5942979

Date: 05/05/23

Amrinder
Sub Divisional Engineer,
Provincial Sub Divn. No 3,
PWD B & R Br., LUDHIANA

Endst. No. 510

Dated: 08-05-23

Copy forwarded to the Principal, St. Martha's Bethany Vidyalaya, Rurka, Mullanpur, Ludhiana for further necessary disposal. No additional/ alternation or expansion and modification to this building is to be carried out without permission of the undersigned.

(Signature)
Executive Engineer,
Provincial Division,
PWD B&R, Ludhiana.